



IECEX Quality Assessment Report

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification Scheme for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Reference No.	DE/PTB/QAR07.0002/07	Status	Current
QAR Free Ref. No.	16-26089	Date of Issue	2017-10-18
Detail of change	manufacturer name is changed to Bürkert Werke GmbH & Co. KG	Valid until	2019-07-20
Site(s) audited	Bürkert Werke GmbH & Co. KG, Christian-Bürkert-Straße 13-17, 74653 Ingelfingen, Germany, Bürkert Werke GmbH & Co. KG, Landauer Straße 24, 74653 Gerabronn, Germany, Bürkert Werke GmbH & Co. KG, Schleifbachweg 40, 74613 Öhringen, Germany, Bürkert + Cie. S.A.S., Triembach au Val, 67220 Ville, France	Audit date	2016-06-08
Issuing ExCB	PTB - Physikalisch-Technische Bundesanstalt (PTB)		
Manufacturer	Bürkert Werke GmbH & Co. KG, Christian-Bürkert-Straße 13-17, 74653 Ingelfingen, Germany		
Country of Manufacturer	Germany		
Product information	solenoides		
Protection concept	Encapsulation "m", Intrinsic Safety "i", Flameproof Enclosure "d", Increased Safety "e", Protection by enclosures "t", type "n"		

Related QARs

DE/PTB/QAR07.0002/00	DE/PTB/QAR07.0002/01	DE/PTB/QAR07.0002/02	DE/PTB/QAR07.0002/03
DE/PTB/QAR07.0002/04	DE/PTB/QAR07.0002/05	DE/PTB/QAR07.0002/06	DE/PTB/QAR07.0002/07

Related Certificates (manual insertion) IECEx PTB 04.0016, IECEx PTB 05.0026 X

Related Certificates (automatic linking)

IECEX BVS 14.0009X issue: 1 IECEx BVS 17.0100X issue: 0

Related Certificates for previous versions

IECEX BVS 11.0083X issue: 0	IECEX BVS 13.0047X issue: 0	IECEX BVS 13.0097X issue: 0	IECEX BVS 13.0105X issue: 0
IECEX BVS 14.0009X issue: 0	IECEX BVS 14.0009X issue: 1	IECEX BVS 14.0035X issue: 0	IECEX BVS 16.0053X issue: 0
IECEX BVS 16.0091X issue: 0	IECEX BVS 17.0100X issue: 0	IECEX EPS 15.0066X issue: 0	IECEX EPS 16.0021X issue: 0
IECEX EPS 16.0021X issue: 1	IECEX EPS 16.0021X issue: 2	IECEX EPS 16.0030X issue: 0	IECEX EPS 16.0049X issue: 0
IECEX EPS 16.0053X issue: 0	IECEX KEM 07.0032 issue: 0	IECEX KEM 07.0033 issue: 0	IECEX PTB 06.0101 issue: 0
IECEX PTB 06.0102 issue: 0	IECEX PTB 07.0021X issue: 0	IECEX PTB 07.0063 issue: 0	IECEX PTB 07.0063 issue: 1
IECEX PTB 08.0016X issue: 0	IECEX PTB 09.0064X issue: 0	IECEX PTB 09.0064X issue: 1	IECEX PTB 10.0019 issue: 0
IECEX PTB 10.0019 issue: 1	IECEX PTB 10.0031X issue: 0	IECEX PTB 12.0040 issue: 0	IECEX PTB 13.0011X issue: 0
IECEX PTB 14.0049X issue: 0	IECEX PTB 14.0049X issue: 1	IECEX PTB 15.0037U issue: 0	IECEX PTB 15.0037U issue: 1
IECEX PTB 16.0014X issue: 0	IECEX PTB 16.0019U issue: 0	IECEX TSA 08.0006X issue: 0	IECEX TSA 08.0006X issue: 1
IECEX TUR 14.0014X issue: 0			

Comments